

25X1

0945Z 22 JAN 63

SECRET

1	4
2	5
3	6

DIRECTOR

25X1

OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

PRIORITY

S/C (17)

25X1

TOR: 1035Z 22 JAN 63

JN 63322

25X1

PRITY

INFO PRITY

CITE

0646

25X1

NO NITE ACTION

25X1

REF A 879

25X1

B 41

C 0371

25X1

1. FROM [] NO VACUUM FAILURE EVIDENT ON POST OP

25X1

25X1

INSPECTION MSN G-3213. VACUUM IS VISUALLY GROUND CHECKED WITH
MSN [] PRIOR TO INSTALLATION IN [] AND IMMEDIATELY
AFTER REMOVAL PRIOR TO UNLOADING []

2. VACUUM VALVE SN-33 WAS USED ON THIS MSN (ALSO ON MSN
G-3215). THIS UNIT WAS DRAWN FROM FAK AND INSTALLED JUST PRIOR
TO G-3213, AFTER ADJUSTMENT AND TREATMENT PER REF B. ONLY CYCLES
WERE 3360 FROM G-3213. TEAR DOWN AFTER MSN REVEALED LITTLE OR
NO WEAR AS REPORTED IN REF C.

25X1

3. [] (REF A) WAS NOT RECEIVED UNTIL AFTER LAUNCH
MSN G-3215.

25 YEAR RE-REVIEW

END OF MESSAGE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.